



Service Bulletin

Bulletin#: 23-03

Date:	11/1/2023
Attention:	[X] Service Manager
Model(s):	42XO-TK011 to TK022 42FXO-TX012 to 031
Subject:	Fireboy Module Replacement
Description:	There may be an internal wiring issue affecting the safety and reliability of the module.
Solution:	Existing module to be replaced with new-PN: 223318. 1. Module is located within the helm 2. Remove the dash brow. This is done by removing the two screws at the forward end of the brow and then lifting the brow off to expose the inside of the helm. 3. Locate the module and replace with the new one. 4. Install brow.
Time Allotted:	2.0 Hours + Travel time if needed. Warranty claim must be filed once work is completed.

The purpose of this work standard is how to access and replace the FireBoy Shutdown module.

- 1. Remove the two screws holding the dash brow in place. Be careful not to damage the vinyl.**



- 2. Gently pull the brow aft and lift up to remove.**



Remove both Screws securing the Fire Boy box and replace with Model ES-3000 Fire Boy

